TECHNICAL BULLETIN 272

EVERLOC+ Compression-Sleeve Tool Service



Product: EVERLOC+ Compression-sleeve Tools

Date: 01 November 2019



REHAU recommends EVERLOC+ compression-sleeve tools be serviced at regular intervals. EVERLOC+ compression-sleeve tools have an internal counter that records the number of completed cycles. When the red LED light (**) slowly flashes for about twenty (20) seconds upon completion of a cycle, the tool requires service.

REHAU recommended interval service includes replacement of the seals / filter / piston / fluid reservoir / hydraulic fluid, cleaning, greasing and an overall assessment to ensure the tool is in proper working order.

EVERLOC+ compression-sleeve tools are to be serviced every two (2) years or after 10,000 compression-sleeve connections, whichever comes first. EVERLOC+ compression-sleeve tools may only be serviced by an Authorized Service Center. Contact your local REHAU sales office or visit www.na.rehau.com/toolservice for instructions for sending tools to the nearest Authorized Service Center.